


D-SUB 19

BOX: VI

Insert Arrangement



Function: Thermometer Read-Out

Date: 24.11.2011

PIN	AMP-BOX	ANSCHLUSS	FUNKTION	BOX VI
1	1	RuOx #0	I+	X1:1
2	2	RuOx #0	U+	X1:2
3	3	FPD	Prim. (I+)	X2:1
4	4	FPD	Sec. (U+)	X2:2
5	5	ET Susz. Th.	Prim. (I+), R(1/4)=1.5kOhm	X3:1
6	6	ET Susz. Th.	Sec. (U+), R(2/3)=14.4kOhm	X3:2
7	7	PdFe Susz. Th.	Prim. (I+), R(1/4)=897Ohm	X4:1
8	8	PdFe Susz. Th.	Sec. (U+), R(2/3)=906Ohm	X4:2
9	-	-	-	X5:1
10	-	shield	-	-
11	19	RuOx #0	I-	X1:4
12	20	RuOx #0	U-	X1:3
13	21	FPD	Prim. (I-)	X2:4
14	22	FPD	Sec. (U-)	X2:3
15	23	ET Susz. Th.	Prim. (I-)	X3:4
16	24	ET Susz. Th.	Sec. (U-)	X3:3
17	25	PdFe Susz. Th.	Prim. (I-)	X4:4
18	26	PdFe Susz. Th.	Sec. (U-)	X4:3
19	-	-	-	X5:4